



NGK Spark Plug - ILFR5B11

RN1637



Replaces

Bosch

FR8MII33X

Specifications

Manufacturer

NGK

Box Quantity

4

Package Quantity

1

Complete Turf Equipment Ltd.

4331 Oil Heritage Road Petrolia, N0N 1R0
519-882-2008

<https://completeturf.rrproducts.com/>