


Replaces John Deere 1420 Rotary Mower Parts



62in & 72in Side & Rear Discharge Deck - Models 2814 60in Deck Parts



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.

| Rep | & R ducts | Mower | Side & Rear Discharge Deck - Models 2814 | | | | | |
|-----------------------------|----------------------------------|----------------------|--|------------|-------------------|--|--|--|
| | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity | | | |
| Rota | · · · | | | | | | | |
| 1 | RTCU15882 | M143749, TCU15882 | Mower Blade - High Lift - 25 x 3 x 1/4 w/.910 Hole | 3 | | | | |
| | Tech Note: Fi | | | | | | | |
| 1 | 1 RTCU15882M | | Mower Blade - Mulching - 25 x 3 x 1/4 w/.910 Hole | 3 | | | | |
| Tech Note: Fits Model 2814: | | | | | | | | |
| Belts | | | | | | | | |
| 20 | RTCU19900 | TCU19900 | Belt - V - Fits 72 in Decks | 1 | | | | |
| | Tech Note: Fits Model 2814 Only: | | | | | | | |
| 20 | RTCU19067 | TCU19067 | V-Belt - (Export Road Homologation) (Use with TCA15323) | 1 | | | | |
| 20 | RTCU13402 | TCU13402 | V-Belt - (Export) | 1 | | | | |
| Other Parts Available | | | | | | | | |
| 42 | RTCU18744 | TCU18744, UC28193 | Wheel - 5 in x 2 3/4 | 2 | | | | |
| 43 | RAM125172 | AM125172 | Wheel Kit - Gage Wheel | 1 | | | | |
| 44 | RM141764 | M141764 | Eyebolt - Includes Flanged Locknut | 1 | | | | |
| 77 | R253-133 | M85699 | Seal - Oil | 3 | | | | |
| 78 | RM88251 | M169375, M88251 | Bearing - Spindle | 6 | | | | |
| 79 | RM127198 | M127198 | Seal | 3 | | | | |
| 80 | R19M7489 | 19M7489 | Bolt Hex HD - M16 x 45 Gr 10.9 | 3 | | | | |
| 81 | RM115245 | M115245 | Roller | 4 | | | | |
| 82 | RM123522 | M123522 | Washer - Belleville - Blade Bolt | 3 | | | | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces John Deere 1420 Rotary Mower Parts



62in & 72in Side & Rear Discharge Deck - Models 2814 60in Deck Parts

| | R&R Part No. | OEM Part No. | Description | Qty Order Req Quantity |
|-----|-----------------|---------------------|---|---|
| 84 | RTCU19299 | TCU19299 | Axle Bushing | 2 |
| 85 | R19M8006 | 19M8006 | Bolt - M8-1.25 x 120 Hx HD Fl Cl 10.9 | 2 |
| 86 | R14M7396 | 14M7396 | Locknut - Flanged Nyloc | 2 |
| 87 | RTCA17524 | TCA17524 | Idler Pulley - 5 in Flat Dia with .75 in Brg ID | 2 |
| 88 | RM141695 | M141695 | Idler - North America (Replaces M112398) | 1 |
| 89 | RAM129501 | AM129501 | Arm | 1 |
| 90 | RM134382 | M134382 | Spindle - 25 mm w/M12-1.75 Blade Bolt Thrd | 3 |
| 91 | RM110057 | M110057 | Shaft - Roller | 2 |
| 92 | R24M7226 | 24M7226 | Washer - 13 x 35 x 5 mm | 1 |
| 93 | RTCU51223 | TCU51223 | Deflector - Grass | 3 |
| 95 | RM136044 | M136044 | Spring - Extension | 1 |
| 96 | RM133598 | M133598 | Shield | 2 |
| 97 | R14M7400 | 14M7400 | Locknut - 10mm | 3 |
| 98 | RTCA13570 | TCA13570 | Bracket | 1 |
| 99 | R24H1308 | 24H1308 | Washer | 1 |
| 100 | R14M7167 | 14M7167 | Nut - M10-1.5 Lock Nylon Insert | 1 |
| 101 | RM163058 | M127517, M163058 | Bushing - Sub For M127517 | 3 |
| 103 | R93-2559 | TCU23201 | Bearing | 2 |
| 104 | RM132309 | M132309 | Spacer | 2 |
| 105 | RM163060 | M133398, M163060 | Washer - Replaces RM133398 | 3 |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.