

## **Coupling - Compression w/Floloc 3/4** RG11207





## Details

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

## Specifications

Manufacturer Manufacturer's Model No Flo Control 112-07

## **Complete Turf Equipment Ltd.** 4331 Oil Heritage Road Petrolia, NON 1R0

4331 Oil Heritage Road Petrolia, NON 1R0 519-882-2008 https://completeturf.rrproducts.com/