



Coupling - Compression w/Floloc 2

RG11220



Details

As cap is tightened, pressure causes the gripping ring to bite into the pipe eliminating pull out.

Specifications

Manufacturer

Flo Control

Complete Turf Equipment Ltd.

4331 Oil Heritage Road Petrolia, N0N 1R0
519-882-2008

<https://completeturf.rrproducts.com/>