



NGK Spark Plug - PFR7S8EG RN1675



Replaces

Bosch

FR6KPP332S

Specifications

Manufacturer NGK

Box Quantity 4

Package Quantity 1

Complete Turf Equipment Ltd.

4331 Oil Heritage Road Petrolia, N0N 1R0
519-882-2008

<https://completeturf.rrproducts.com/>