



# NGK Spark Plug - BR6HS

RN3922



## Replaces

AC Delco	R42CF, R42F
Autolite	3686
Bosch	WR7A, WR7AC
Champion	830, 931-1, 931M, 931S, 933-1, 933M, 933S, QL7J5, QL82C, QL86, QL86C, RL7J, RL82, RL85, RL86, RL86C
Denso	W20FSR, W20FSRU
R&R Products	R121-0547
Toro	121-0547

## Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

## Fits Models

Toro Greensmaster 1000  
Toro Greensmaster 1010  
Toro Greensmaster 1600  
Toro Greensmaster 1610  
Toro Greensmaster 800  
Toro Greensmaster Flex 1800  
Toro Greensmaster Flex 1820  
Toro Greensmaster Flex 2100  
Toro Greensmaster Flex 2120

## Complete Turf Equipment Ltd.

4331 Oil Heritage Road Petrolia, N0N 1R0  
519-882-2008

<https://completeturf.rrproducts.com/>