

## **1/2 PVC Union Split Nut Kit** RGSNK005





## **Details**

Split Nut Repair Kit is designed to replace broken union nuts on all True Union 2000 Ball Valves and Sch 80 Union 2000 fittings.

Kit includes: 2-Split Nut Halves 1-SS316 Gear Clamp. Full valve pressure rating maintained.

## **Specifications**

Manufacturer	Spears
Box Quantity	25
Fitting Size	1/2
Package Quantity	1

**Complete Turf Equipment Ltd.** 4331 Oil Heritage Road Petrolia, NON 1R0 519-882-2008