

2-1/2,3 Viton T/U Ball Valve Repair

RGTUVRK030





Details

Ball Valve Kit includes: 2-PTFE Seats, 2-Seat O-rings (2-1/2"), 2-End Connector O-rings, 1-Stem Bearing (1-1/4" & up).

Specifications

Manufacturer Manufacturer's Model No Seal Type Spears TU-VRK-030

Viton

Complete Turf Equipment Ltd. 4331 Oil Heritage Road Petrolia, NON 1R0

4331 Oil Heritage Road Petrolia, NON 1R0 519-882-2008 https://completeturf.rrproducts.com/